

161630Z JAN 02 PRESINSURV NORFOLK VA(n) CORRECTION

TO CNO WASHINGTON DC(n)  
CINCLANTFLT NORFOLK VA  
CINCPACFLT PEARL HARBOR HI  
COMNAVSURFLANT NORFOLK VA  
COMNAVSURFPAC SAN DIEGO CA(n)  
COMNAVAIRLANT NORFOLK VA  
COMNAVAIRPAC SAN DIEGO CA  
COMSUBLANT NORFOLK VA  
COMSUBPAC PEARL HARBOR HI  
COMSCLANT NORFOLK VA  
COMSCPAC SAN DIEGO CA(n)  
COMINEXWARCOM CORPUS CHRISTI TX  
COMNAVSPECWARCOM CORONADO CA(n)  
CC COMNAVSEASYS COM WASHINGTON DC(n)  
COMSPAWARSYS COM SAN DIEGO CA(n)  
PEO CARRIERS WASHINGTON DC  
PEO THEATER SURFACE COMBATANTS WASHINGTON DC  
PEO EXW WASHINGTON DC  
COMSC WASHINGTON DC(n)  
COGARD ENGLOGCEN BALTIMORE MD  
CNET PENSACOLA FL  
MSC NFAF WEST SAN DIEGO CA  
MSC NFAF EAST NORFOLK VA  
NETPDTC PENSACOLA FL  
NAVICP MECHANICSBURG PA(n)  
NAVSCSCOL ATHENS GA  
SUPSHIP BATH ME  
COMNAVSUPSYSCOM MECHANICSBURG PA(n)  
NAVMELOGCOM FT DETRICK MD(n)  
NAVSURFWARCEN SHIPSYSENGSTA PHILADELPHIA PA(n)  
COMNAVSAFECEN NORFOLK VA(n)  
NEXCOM NORFOLK VA  
SERVSCOLCOM GREAT LAKES IL(n)  
COMAFLOATRAGRU ATLANTIC NORFOLK VA(n)  
COMAFLOATRAGRUPAC SAN DIEGO CA  
SWOSCOLCOM NEWPORT RI(n)  
COMNAVSURFRESFOR NEW ORLEANS LA  
INSURVPAC SAN DIEGO CA(n)  
INSURVLANT NORFOLK VA  
INSURVLANT NORFOLK VA(n)  
FTSCLANT NORFOLK VA  
FTSCPAC SAN DIEGO CA

UNCLAS

FM PRESINSURV NORFOLK VA  
TO CNO WASHINGTON DC  
CNO WASHINGTON DC(n)  
CINCLANTFLT NORFOLK VA  
CINCPACFLT PEARL HARBOR HI(n)  
CINCPACFLT PEARL HARBOR HI  
COMNAVSURFLANT NORFOLK VA  
COMNAVSURFPAC SAN DIEGO CA(n)  
COMNAVSURFPAC SAN DIEGO CA  
COMNAVAIRLANT NORFOLK VA(n)

COMNAVAIRLANT NORFOLK VA  
 COMNAVAIRPAC SAN DIEGO CA  
 COMSUBLANT NORFOLK VA  
 COMSUBPAC PEARL HARBOR HI  
 COMSCLANT NORFOLK VA  
 COMSCPAC SAN DIEGO CA  
 COMINELWARCOM CORPUS CHRISTI TX  
 COMNAVSPECWARCOM CORONADO CA  
 CC COMNAVSEASYS COM WASHINGTON DC(n)  
 COMNAVSEASYS COM WASHINGTON DC  
 COMSPAWARSYS COM SAN DIEGO CA  
 PEO CARRIERS WASHINGTON DC(n)  
 PEO CARRIERS WASHINGTON DC  
 PEO THEATER SURFACE COMBATANTS WASHINGTON DC(n)  
 PEO THEATER SURFACE COMBATANTS WASHINGTON DC  
 PEO EXW WASHINGTON DC(n)  
 PEO EXW WASHINGTON DC  
 COMSC WASHINGTON DC(n)  
 COGARD ENGLOGCEN BALTIMORE MD  
 CNET PENSACOLA FL  
 MSC NFAF WEST SAN DIEGO CA  
 MSC NFAF EAST NORFOLK VA  
 NETPDTC PENSACOLA FL  
 NAVICP MECHANICSBURG PA  
 NAVSCSCOL ATHENS GA  
 SUPSHIP BATH ME  
 COMNAVSUPSYSCOM MECHANICSBURG PA  
 NAVMEDLOGCOM FT DETRICK MD  
 NAVSURFWARCEN SHIPSYSENGSTA PHILADELPHIA PA  
 COMNAVSAFECEN NORFOLK VA(n)  
 COMNAVSAFECEN NORFOLK VA  
 NEXCOM NORFOLK VA  
 SERVSCOLCOM GREAT LAKES IL  
 COMAFLOATRAGRU ATLANTIC NORFOLK VA  
 COMAFLOATRAGRUPAC SAN DIEGO CA  
 SWOSCOLCOM NEWPORT RI(n)  
 SWOSCOLCOM NEWPORT RI  
 COMNAVRESFRESFOR NEW ORLEANS LA  
 INSURVPAC SAN DIEGO CA(n)  
 INSURVPAC SAN DIEGO CA  
 INSURVLANT NORFOLK VA(n)  
 INSURVLANT NORFOLK VA  
 FTSCCLANT NORFOLK VA  
 FTSCPAC SAN DIEGO CA  
 MSGID/GENADMIN/PRESINSURV//  
 SUBJ/CORRECTION (1) INSURV SURFACE SHIP MESSAGE NR 012//  
 REF/A/PUB/NAVSEA/28FEB1995//  
 REF/B/PUB/NAVSEA/01DEC1994//  
 REF/C/PUB/NAVSEA/29MAR1991//  
 REF/D/MSG/NSWC PHILADELPHIA/211930ZJUL1997//  
 REF/E/INST/OPNAVINST 9640.1A/03SEP1996//  
 AMPN/NONE AT THIS TIME//  
 NARR/REF A IS NAVSEA TECHNICAL MANUAL FOR LAUNDRY AND DRY  
 CLEANING. REF B IS SHIPBOARD LAUNDRY AND DRY CLEANING EQUIPMENT  
 CATALOG. REF C IS SHIPBOARD HEATING VENTILATION AND COOLING  
 DESIGN CRITERIA MANUAL. REF D IS ISE ADVISORY 010-97. REF E IS  
 OPNAV INSTRUCTION FOR SHIPBOARD HABITABILITY PROGRAM.//

POC/J. M. ADAMS/CDR/SURFACE TRIALS/LOC:NORFOLK VA  
/EMAIL:DSN: 253-7578 EXT 3029//  
POC/PAULL/LT/INSURVPAC/LOC:SAN DIEGO CA/TEL:COMM: (619)556-0146//  
POC/MAGIERA/LCDR/INSURVLANT/LOC:NORFOLK VA  
/EMAIL:COMM: (757)462-7881 EXT 3096//

RMKS/1. FOR TYCOMS: REQUEST THIS MESSAGE BE READDRESSSED FOR  
WIDEST DISSEMINATION TO SURFACE UNITS AND ISICS.

2. CONTENTS: THIS IS ONE IN A SERIES OF INSURV  
MESSAGES INTENDED TO IMPROVE THE SURFACE FLEET'S MATERIAL  
READINESS BY PROVIDING CO'S INFORMATION THAT WILL HELP THEM  
MAINTAIN THEIR SHIPS. THIS MESSAGE ADDRESSES THE FOLLOWING  
SUPPLY (SP) AND HABITABILITY (HB) ISSUES:

- SELF-SERVICE LAUNDRY
- APPROVED GALLEY DEEP FAT FRYER (DFF)
- DFF SECONDARY THERMOSTAT TESTING PMS PROCEDURES
- PREPARING FOR THE MATERIAL INSPECTION
- SUPPLY MATERIAL INSPECTION OVERVIEW
- HABITABILITY MATERIAL INSPECTION OVERVIEW

3. SELF-SERVICE LAUNDRY: SELF-SERVICE LAUNDRIES MUST USE AUTHORIZED  
HEAVY-DUTY, COMMERCIAL EQUIPMENT, INSTALLED IN DESIGNATED,  
AUTHORIZED COMPARTMENTS IN ACCORDANCE WITH APPLICABLE GENERAL  
SPECIFICATIONS FOR OVERHAUL (GSO) REQUIREMENTS.

A. SHIP'S FORCE INITIATED INSTALLATION OF SELF-SERVICE LAUNDRIES  
OFTEN USE UNAUTHORIZED HOUSEHOLD EQUIPMENT (I.E., STACKABLE  
COMBINATION WASHER-DRYER UNITS) THAT ARE NOT INSTALLED IAW SHIPBOARD  
SPECIFICATIONS. THEY ARE OFTEN ALSO INSTALLED IN UNAUTHORIZED  
SPACES, SUCH AS CLEANING GEAR LOCKERS OR SANITARY SPACES. WASHERS  
MUST BE INSTALLED INSIDE A COMBING TO PREVENT FLOODING IN CASE OF  
MACHINE MALFUNCTION OR INADVERTENT

ISOLATION OF A DRAIN CUT OUT VALVE. DRYERS MUST HAVE AN EMERGENCY  
DISCONNECT SWITCH OR MEANS TO ISOLATE ELECTRICAL POWER FROM OUTSIDE  
THE SPACE IN CASE OF ALPHA OR CHARLIE FIRES. ADDITIONALLY, EXHAUST  
DUCTING FOR DRYERS MUST VENTILATE DIRECTLY OVERBOARD, NOT INTO THE  
SHIP'S RECIRC SYSTEM OR DIRECTLY INTO THE SPACE. A SECONDARY LINT  
TRAP SIMILAR TO THE SYSTEMS IN THE SHIP'S LAUNDRY MUST BE USED.

B. FAILURE TO ADHERE TO THE REQUIREMENTS FOR LINT TRAPS WILL LEAD TO  
A SIGNIFICANT AMOUNT OF LINT ACCUMULATION IN THE DUCTS AND THE  
SUBSEQUENT POTENTIAL FIRE HAZARD, THREATENING SPACES SERVICED BY THE  
VENTILATION SYSTEM.

ADDITIONAL PROBLEMS CAUSE BY UNAUTHORIZED INSTALLATIONS INCLUDE:

- UNITS ARE NOT/CANNOT BE PROPERLY SECURED WITH SWAY BRACING  
CREATING A SAFETY HAZARD.
- REDUCED RELIABILITY AND INCREASED DOWNTIME.
- REDUCED LOAD CAPACITY.
- 1:1 RATIO DOES NOT ALLOW FOR THE DESIGN GOAL OF 3 DRYERS PER 2  
WASHERS.
- ELIMINATES FLEXIBILITY OF SINGLE MACHINE REPLACEMENT.

4. AS PER REF A, SELF SERVE LAUNDRY EQUIPMENT SHALL BE  
NON-STACKABLE, COMMERCIAL GRADE AS APPROVED BY THE LIFE CYCLE  
EQUIPMENT MANAGER. SPECIFIC TYPES OF WASHERS AND DRYERS THAT HAVE  
THE CAPACITY OF BEING "STACKED" CAN BE AUTHORIZED. PRIMARY  
ADVANTAGES TO THESE TYPES OF UNITS OVER STANDARD STACKABLE UNITS ARE  
HIGHER CAPACITY, REDUCED WATER CONSUMPTION, STRONGER DRYER BASE  
WHICH BEARS 100 PERCENT ON WASHER TOP, AND INCREASED DURABILITY.  
ALL UNITS MUST BE APPROVED BY THE LIFE CYCLE MANAGER, MR. JOE BOWEN,  
NAVSEA CODE 9783, (215)897-7925,  
AND MEET SAFETY AND PERFORMANCE STANDARDS REQUIRED BY REFS A AND B.

WHEN INSTALLED, UNITS MUST BE PROPERLY SECURED WITH SWAY BRACING AND PROPER VENTILATION PROVIDED AS REQUIRED BY REF C.

5. APPROVED GALLEY DEEP FAT FRYER (DFF): SHIPBOARD DEEP FAT FRYERS ARE REQUIRED TO HAVE A SECONDARY THERMOSTAT THAT IS NONADJUSTABLE (PART OF A MANUAL RESET TYPE CIRCUIT) AND INSTALLED IN CONJUNCTION WITH A SHUNT TRIP FOR EACH DFF UNIT LOCATED IN THE ELECTRICAL DISTRIBUTION PANEL. WHEN PROPERLY INSTALLED AND MAINTAINED, THIS SYSTEM CAUSES DFF TO BE DEENERGIZED WHEN THE TEMPERATURE OF THE OIL REACHES 430 TO 460 DEGREES FAHRENHEIT.

A. THE FOLLOWING ARE THE APPROVED MAKES AND MODELS OF DEEP FAT FRYERS:

MAKE (CAGE)  
FRYMASTER (95284)  
H14SC-NSU 7310-01-391-9564  
H17SC-NSU 7310-01-391-9561  
H22SC-NSU 7310-01-314-1204  
NEW FRYMASTER UNITS  
FPH117SC SINGLE UNIT  
FPH217SC TWO BANK UNIT  
FPH317 THREE BANK UNIT  
FPH417SC FOUR BANK UNIT  
LANG (34931) USN-50 NSN PENDING  
EXACT REPLACEMENT FOR HOBART MODEL  
NDK50 USN  
MIDDLEBY (78770) (FORMERLY TOASTMASTER (TM))  
N1403 7310-01-103-9947 (TM MODEL 1403)  
N1405 7310-01-103-9949 (TM MODEL 1405)  
N1409 7310-01-205-2444 (TM MODEL 1499)

B. REF D ALLOWS HOBART MODELS BUILT PRIOR TO 1995 (NO LONGER AUTHORIZED) TO REMAIN IN USE UNTIL THE END OF THEIR SERVICEABLE LIFE.

C. ENGINEERING AND SUPPLY DEPARTMENTS SHOULD VALIDATE THE TYPE OF UNITS INSTALLED, DATE OF MANUFACTURE AND IF UNIT(S) ARE REACHING END OF EXPECTED SERVICEABLE LIFE, WHAT PLANS ARE BEING MADE TO REPLACE WITH ONE OF THE MODELS LISTED ABOVE.

6. DFF SECONDARY THERMOSTAT TESTING PROCEDURES: PMS PROCEDURES ARE PROMULGATED UNDER MIP 6539/001-38 MRC Q-1R, Q-2R OR Q-5R AND ARE PERFORMED BY AN EM. TESTING OF SECONDARY THERMOSTAT SWITCHES SHOULD BE ACCOMPLISHED BY ONE OF THE FOLLOWING TWO METHODS IAW THE APPLICABLE MRC. ALTHOUGH ACCOMPLISHED BY ENG DEPT, GALLEY WATCH TEAMS SHOULD KNOW WHEN THE TESTING IS DONE. IT IS ALSO A GOOD OPPORTUNITY FOR THE SUPPLY KHAKI AND FOOD SERVICE PERSONNEL TO LEARN ABOUT THEIR EQUIPMENT BY OBSERVING THIS PMS CHECK.

A. FIRST METHOD, SECONDARY THERMOSTAT TEST SWITCH INSTALLED: THIS SIMPLE CHECK ONLY REQUIRES THE MAINTENANCE PERSON TO HOLD THE SWITCH DOWN AND VERIFY THE OIL TEMPERATURE IS BETWEEN 430 AND 460 DEGREES FAHRENHEIT WHEN THE SHUT DOWN OF THE ELECTRICAL SYSTEM OCCURS. THIS IS THE PREFERRED METHOD BECAUSE IT MINIMIZES TIME REQUIRED TO COMPLETE THE CHECK. IF A TEST SWITCH IS NOT INSTALLED CONTACT THE MANUFACTURER FOR THE CORRECT PART NR TO USE ON THE PARTICULAR MODEL. IF THE UNIT IS CONFIGURED FOR A TEST SWITCH, INSTALLATION CAN BE COMPLETED BY SHIP'S FORCE.

B. SECOND METHOD, SECONDARY THERMOSTATIC TEST SWITCH NOT INSTALLED:

THE PRIMARY THERMOSTATIC SWITCH THAT LIMITS THE TEMPERATURE OF THE OIL TO 425 DEGREES FAHRENHEIT IS BYPASSED BY TAGGING OUT THE

UNIT, JUMPERING AROUND THE PRIMARY THERMOSTAT, CLEARING THE TAG, THEN RETURNING POWER TO THE UNIT FOR TESTING. THE SAME CHECK IS THEN CONDUCTED TO VERIFY THE FRYER SHUTS DOWN WHEN THE OIL REACHES A TEMPERATURE OF 430 TO 460 DEGREES FAHRENHEIT. UPON COMPLETION OF THE CHECK ELECTRICAL POWER TO THE UNIT IS SECURED, THE UNIT IS TAGGED OUT, THE JUMPER WIRES REMOVED, TAGS CLEARED AND THE UNIT IS RETURNED TO NORMAL OPERATION.

7. PREPARING FOR THE MATERIAL INSPECTION (MI). THE SUPPLY (SP) AND HABITABILITY (HB) PORTIONS OF THE MI HAVE BEEN COMBINED INTO ONE METRIC CALLED QUALITY OF SHIPBOARD LIFE (QSL). THE QSL SCORE IS DERIVED FROM COMBINING THE EQUIPMENT OPERATIONAL CAPABILITY (EOC) SCORES OF THE SP AND HB INSPECTIONS. THE EOC FOR ANY PARTICULAR PIECE OF EQUIPMENT IS DERIVED FROM OPERATING THE EQUIPMENT TO ASSESS HOW WELL IT PERFORMS ITS INTENDED PURPOSE. THE MAJORITY OF CHECKS ARE BASED ON PMS AND TECH MANUAL STANDARDS. THE MOST EFFECTIVE METHOD OF PREPARING FOR THE MI IS TO ENSURE THAT ALL EQUIPMENT IS OPERABLE. IN PARTICULAR, FOCUSING ON THE MAJOR PIECES OF SUPPLY EQUIPMENT LISTED IN PARAS 8 AND 9 WILL IMPROVE MI RESULTS AS WELL AS SUPPLY/HAB READINESS.

8. THE FOLLOWING PARAGRAPH PROVIDES AN OVERVIEW OF SPECIFIC DEFICIENCIES MOST COMMONLY FOUND ON MAJOR PIECES OF SUPPLY EQUIPMENT. THESE ITEMS HAVE THE GREATEST IMPACT HOW THE SHIP SUPPLY DEPARTMENT IS ASSESSED DURING THE MATERIAL INSPECTION.

A. DEEP FAT FRYERS:

- NO EMERGENCY DISCONNECT SWITCH INSTALLED.
- OVER-TEMP SHUNT TRIP FAILURE.
- UNIT NOT CALIBRATED.

B. DISHWASHERS:

- WASH, RINSE AND FINAL RINSE TEMPS NOT REACHED.
- GAUGES INOP OR NOT INSTALLED.
- FINAL RINSE PRESSURE (20PSI) NOT REACHED.

C. OVENS:

- UNIT NOT CALIBRATED.
- MIRROR DOORS, DOOR SAFETY LATCH BROKEN.
- TIMER, LIGHT OR BLOWER INOP.

D. STEAM KETTLES:

- COVER LATCH BACK DEVICE BROKEN.
- RELIEF VALVE NOT HYDROSTATICALLY TESTED OR PULL CHAIN BROKEN.
- HAND WHEELS BROKEN OR MISSING.

E. STEAM TABLES:

- FOOD WELLS INOP, DO NOT HEAT TO 180 DEG F.
- MISSING DRAINLINE STRAINERS.

F. ELECTRIC GRIDDLES:

- UNIT NOT CALIBRATED.
- GREASE TRAP WARPED OR BROKEN.
- WIRES HANGING IN GREASE TRAP.

G. GAYLORD HOODS:

- AIR FLOW NOT 1000 FPM.
- PRESSURE/TEMP GAUGE INOP OR NOT REACHING 30 PSI AND 160 DEG F.
- DETERGENT PUMP INOP.
- WASHDOWN LEAKS ONTO ELECTRICALLY OPERATED EQUIPMENT.
- NOZZLES CLOGGED OR POINT IN WRONG DIRECTION.

H. REACH-IN REEFERS:

- UNIT IS BEYOND SERVICABLE LIFE, AND NOT REPLACED.
- DOOR LATCH BROKEN, GASKET CRUSHED.
- UNIT DOES NOT MAINTAIN TEMP.

I. ICE MACHINES:

- UNIT IS INOP.

J. DEEP SINKS:

- BOOSTER HEATER CLOGGED WITH DEBRIS.
- BOOSTER HEATER FAILS TO MAINTAIN 180 DEG F.
- LOW WATER/HIGH TEMP LIGHT INOP.

K. PRESSURE COOKERS:

- DOOR GASKET LEAKS.

L. STOREROOMS:

- DECK GRATING NOT SECURE, TRIP HAZARDS.
- MISSING BATTENS, MATERIAL NOT SECURE FOR SEA.

M. REFRIGERATED STOREROOMS:

- SELF-FALLING DOOR LATCH BROKEN.
- INOP LIGHTING.

N. LAUNDRY WASHERS-EXTRACTORS:

- WATER DOES NOT REACH 130 F.
- THERMOSTAT NOT SET TO WASH FORMULA TEMPERATURE.
- INOPERATIVE DRAIN VALVES.
- INNER DOOR HINGE AND LATCH OUT OF ALIGNMENT.
- WASH MOTOR BRAKE REQUIRES ADJUSTMENT.

O. TUMBLERS- DRYERS:

- THERMOSTATS AND THERMOMETERS NOT CALIBRATED.
- DISPLACED CAPILLARY TUBES.
- PRIMARY AND SECONDARY LINT FILTERS NOT CLEANED.
- BASKET AND DOOR NOT ALIGNED.
- DOOR SWITCH INOP.

P. LAUNDRY PRESSES:

- LACK OF MAINTENANCE/CLEANING.
- INOPERATIVE SAFETY BAR/RELEASE MECHANISM.
- HOODS NOT ATTACHED PROPERLY.
- INOPERATIVE PRESS CONTROLS.
- DETERIORATED COVERS AND PADS.
- FOR MORE SPECIFIC OR ADDITIONAL INFO ON THE ABOVE ITEMS

CONTACT POC'S LISTED IN MESSAGE HEADER.

9. THE FOLLOWING PARAGRAPH PROVIDES AN OVERVIEW OF THE HABITABILITY MI, LISTING SPECIFIC DEFICIENCIES FOUND IN THE AREA OF HABITABILITY. THESE ITEMS ARE THE MOST COMMONLY FOUND IN THE FLEET AND HAVE THE GREATEST IMPACT HOW SHIPBOARD HABITABILITY IS ASSESSED DURING THE MATERIAL INSPECTION.

A. BERTHING COMPARTMENTS:

- BUNK ITEMS NOT INSTALLED INCLUDING CURTAINS, CORRECT SIZE MATTRESS, LIGHT, FAN OR HVAC VENT, SAFETY STRAP (SMALL SHIPS), GRAB ROD, TOWEL BAR AND LINENS.
- RED LIGHTING NOT OPERABLE OR INSUFFICIENT TO SAFELY LIGHT THE ENTIRE COMPARTMENT.
- LOCKERS NOT NUMBERED OR ARE BROKEN.
- DECK COVERING IS CHIPPED, GOUGED, NOT MAINTAINED OR DIRTY.
- MIRRORS NOT INSTALLED, SCRATCHED OR BROKEN.
- MIRROR LIGHTS INOP.

B. SANITARY SPACES:

- COMMODES ARE INOP OR CRACKED.
- SINKS AND FAUCETS INOP, WITHOUT STOPPERS OR LEAKING.
- STALL DOORS ARE BROKEN OR DO NOT LATCH.
- MIRRORS ARE SCRATCHED OR BROKEN.
- SHOWERS MISSING SOAP DISHES, GRAB RODS, CURTAINS OR FLOOR MATS.
- SHOWERS ARE RUSTED OR POORLY PRESERVED.
- DECK COVERING IS CHIPPED, GOUGED, NOT MAINTAINED OR DIRTY.
- VENTILATION AIRFLOW DOES NOT MEET DESIGN SPECIFICATIONS.

C. CREW LOUNGES:

- ARE NOT PROVIDED IN ACCORDANCE WITH REF E.
- TABLES AND CHAIRS ARE MISSING OR BROKEN.//